

AVIONS PIERRE ROBIN

DIJON

France

S E R V I C E

SERVICE BULLETIN NR 73

SUBJECT : Replacement of the 50 A fuse

AIRCRAFT CONCERNED : R 2100 - R 2100 A - R 2160 : up to nr 128 inclusive

DATE : 27.02.1978

Page 1/1

APPLICATION : Before August, 31th 1978

Approved by D.G.A.C.

The breaker located on the instrument panel on the right of the circuit breakers side passanger must be a 40 A breaker.

If that is not the case, replace it before August, 31th 1978

To replace the breader, proceed as follows :

- Unscrew the nut of the breaker in place
- Place a 40 A breaker
- Screw the nut

Our After-Sale Services are at your disposal to provide you in 40 A breakers.

R
E
C
O
M
M
E
N
D
E
D