AVIONS PIERRE ROBIN

Aérodrôme de DIJON-VAL SUZON

21121 Fontaine .lès .Dijon

Tel. (80) 31 61 01 ___ Telex 350 818

FRANCE

LETTRE DE SERVICE
SERVICE LETTER

N° 17

Objet Object : RECTIFICATION DES BULLETINS DE SERVICE N° 84 - 85 - 86.
RECTIFICATION SERVICE BULLETIN N° 84 - 85 - 86

Avions concernés : Voir bulletin de service

Aircrafts concerned : See Service Bulletin

Date	**Edition** Issue	**Page**
septembre 1980 *september 1980*	1	1/1

Une erreur s'est glissée dans les Bulletins de service n° 84 - 85 - 86 du mois de juillet 1980, relative à la mention : AVIONS CONCERNES

Il faut lire :

Bulletin de service n° 84 : Avions concernés : R 2000 tous types

Bulletin de service n° 85 : Avions concernés : R 2000 tous types

Bulletin de service n° 86 : Avions concernés : DR 400 jusqu'au n° 1489
R 1000 jusqu'au n° 268
R 2000 jusqu'au n° 191
HR 100 tous numéros

Merci d'apporter cette modification sur vos bulletins de service.

- - - - - - - -

There is a mistake in Service Bulletins nr 84 - 85 - 86 date july 1980, about mention of : AIRCRAFTS CONCERNED

Must read :

Service Bulletin nr 84 : Aircrafts concerned : R 2000 all types

Service Bulletin nr 85 : Aircrafts concerned : R 2000 all types

Service Bulletin nr 86 : Aircrafts concerned : DR 400 up to serial 1489
R 1000 up to serial 268
R 2000 up to serial 191
HR 100 all nr

Thank you for your attention.