

AVIONS PIERRE ROBIN

DIJON

France

SERVICE

SERVICE BULLETIN N° 58

Object : Replacement of engine flexible baffles.
Aircraft concerned : All DR 400, up to n° 1019 inclusive except :
n° 984 - 1000 - 1007 to 1014
All HR 100/200 B
All HR 100/210, up to n° 204 inclusive
All HR 100/285 TIARA, up to n° 509 inclusive, except
n° 508
All HR 200, up to n° 62 inclusive

Date : 24/02/75

Date of application : Major Inspection
at the latest.

Approved by S.G.A.C.

In order to improve service life and provide better sealing at the front of the engine bay, it is requested that engine flexible baffles fitted to the aircraft listed above should be replaced.

This operation should be carried out, at the latest, during the next Major Inspection and consists in replacing the existing rubber baffles by baffles made of Neoprene-impregnated asbestos material.

A replacement Kit may be ordered from our After Sale Service under the reference n° 95-94-86, indicating the type of aircraft for which it is intended, e.g. :

1 Kit of baffles n° 95-94-86, for DR 400/140.

The flexible baffles-to-metal baffles attachment remains unchanged.

IMPERATIVE