

AVIONS ROBIN

1, route de Troyes 21121 DAROIS - FRANCE Tél. 33 (0)3 80 44 20 50 Fax: 33 (0)3 80 35 60 80

BULLETIN SERVICE N°155 rév.1/SERVICE BULLETIN N°155 rev.1

IMPERATIF

OBJET

UTILISATION EN CATEGORIE UTILITAIRE
DE L'AVION R2160 ET R2160D

AVIONS CONCERNES

R2160 tous NS
R2160D jusqu'au NS 264 inclus si masse de
décollage à 900 kg

DELAI D'APPLICATION

A la prochaine visite de 100 heures

APPROBATION DGAC

13.11.98

Suite à des essais en vol, les vitesses de décro-
chage initialement calculées ont été modifiées.

Nous vous prions de réaliser les actions suivantes
à la prochaine visite de 100 h:

1 - Insérer la page jaune temporaire ci-jointe dans
votre manuel de vol, en attente de la parution
du manuel de vol révisé. Voir § 3.

2 - Modifier le marquage de l'anémomètre selon le
tableau ci-dessous:

Arc vert: 117 km/h (63 kt) - 236 km/h (127 kt)
Arc blanc: 94 km/h (51 kt) - 180 km/h (97 kt)

Vérifier l'étanchéité de la statique instrument.

3 - Commander le manuel de vol dernière édition
en précisant la langue dans laquelle vous le
souhaitez, ainsi que l'immatriculation et le
numéro de série de votre appareil, auprès de
notre service après vente:

MANDATORY

SUBJECT

USE IN UTILITY CATEGORY
OF THE R2160 AND R2160D AIRCRAFT

AIRCRAFT AFFECTED

R2160 all SN
R2160D to SN 264 included if T/O weight
increased to 900 kg (1984 lb)

TIME OF COMPLIANCE

At the next 100 hour visit

DGAC APPROVAL

13.11.98

*After a flight test the initially calculated stall speeds
have been modified.*

*Following operations have to be carried out at the
next 100 h visit:*

1 - Insert the yellow temporary page here- enclosed
in your flight manual, awaiting the issue of the
revised flight manual. See § 3.

2 - Modify the markings of the airspeed indicator
according to the following table:

Green arc: 117 km/h (63 kt) - 236 km/h (127 kt)
White arc: 94 km/h (51 kt) - 180 km/h (97 kt)

Insure that the instrument static line is free of
leaks.

3 - Order the latest edition of the flight manual by
specifying the language in which you want it,
and the registration and serial number of your
aircraft to our after sale service:

ROBIN SA

1, route de Troyes
21121 DAROIS - FRANCE
Tél. 33 (0)3 80 35 61 98 Fax: 33 (0)3 80 35 60 58

Le BS n°155 du 9/10/97 est annulé et remplacé par
la présente révision.

*The SB nr 155 dated 9/10/97 is cancelled and
superseded by the present revision.*